QFA-A01-B03

Service Information

Issued by RJA

MODEL: XP-60/80, JD-990

DATE: 2001/11/09

Information No. 101439

SUBJECT: LCD UNIT IS CHANGED

[SYMPTOM]

Since Old LCD UNIT(LCM32080YGV:#15029559) is difficult to obtain, it will be changed to LCD UNIT(LCM32080YGV2:#01908267).

[CHANGE/MODIFICATION]

The Main board will be changed, too, because the new and old parts of the LCD require different specifications of contrast.

MODEL (MAIN BOARD)	No.	OLD	NEW
XP-60 (#17048479) XP-80 (#17048359)	R107		47K ohm #15399437
	R108	100K ohm #15399445	82K ohm #15399443
	R113	6.8K ohm #15399417	Control of the Contro
JD-990 (#7969290000)	R9	2K Ohm #15399488	1.8K ohm #15399403
	R13	22K ohm #15399429	18K ohm #15399427
	R14	10K ohm #15399421	6.8K ohm #15399417

[PARTS]

#01908267 ---- LCD UNIT LCM32080YGV2 (NEW)

#17048479 ---- MAIN BOARD ASSY XP-60 (constant for new LCD UNIT)
#17048359 ---- MAIN BOARD ASSY XP-80 (constant for new LCD UNIT)
#15399437 ---- MTL. FILM RESISTOR RPC10T 473 J 1/10W 47K ohm for XP-60/80
#15399443 ---- MTL. FILM RESISTOR RPC10T 823 J 1/10W 82K ohm for XP-60/80
#15399419 ---- MTL. FILM RESISTOR RPC10T 822 J 1/10W 8.2K ohm for XP-60/80

#7969290000 ---- MAIN BOARD ASSY JD-990 (constant for old LCD UNIT)
#15399403 ---- MTL.FILM RESISTOR RPC10T 182 J 1/10W 1.8K ohm for
JD-990

```
#15399427 ---- MTL.FILM RESISTOR RPC10T 183 J 1/10W 18K ohm for JD-990 #15399417 ---- MTL.FILM RESISTOR RPC10T 682 J 1/10W 6.8K ohm for JD-990
```

[EFFECTIVE]

```
XP-80 ---- S/No. CM57050 up (from August 1999 Production) XP-60 ---- S/No. AM55000 up (from August 1999 Production) JD-990 ---- No production.
```

[SERVICE RESPONSE]

 When you change the LCD UNIT or MAIN BOARD, please add the above change to the unit.